



Highways Activity Log 2023 - 2024

Date Reported	Reporter (NK = Not Known)	Track No.	Fault	Location	Details	Status
03.01.2023	Dick	21636941	Outdated advisory signs still in situ	Woolton Hill Road Jct of Trade Street and Ball Hill side of Fullers Lane	Signs indicate works for 16.12.2022, now well out of date. Request update or remove	Complete
21.02.2023	Dick	7116735	Ongoing water seepage	Woolton Hill Road opposite access to Junior School	Continued water seepage onto pavement and road. Sothern Water informed and attended x4 but determined not due to mains or sewerage. Hence referred to HCC Highways ref possible groundwater backed up.	22.02.2023: Resolved.
25.02.2023	Dick	21651762	Deep pothole	Woolton Hill Road/ Ball Hill	Temporarily marked by hazard bollard. Previously reported by MoP, but now upgraded due to worsening state of hole and traffic hazard for converging traffic near blind bend.	14.03.2023: Passed to contractor 07/09/2023: Enquiry closed
07.03.2023	Dick		Multiple hazards	A343 - A34	Multiple potholes and carriage degradation additionally reported by various sources (see also ref . 104576272 March 2022). Mails sent to K Malthouse MP; Cllr Thacker, HCC Highways.	27.03.2023: Warning signs and some temporary patching. See full report to EWPC 27.03.2023 6 Oct 2023: resurfaced (see 11.03.2022)
05.04.2023	White	21662291	Major potholes	Ball Hill Road, Hatt Common	Deep pothole opposite Garage	Reported as completed although no evidence of corrective action.
05.04.2023	Dick	21662426 (See also 104519025)	Road degradation	Ball Hill Road/ Watery Lane: Gore End westward to county boundary	Road extending from Hilliers Farm at Gore End westward to county boundary showing severe degradation with pothole avoidance causing hazard for opposing vehicles.	13.04.2023: email from Highways Area Manager: Highways engineer investigated/advised carriageway monitored for potholes and infilling where applicable. Follow up order for dragon patching with road visited regularly. Drainage issues to be checked in coming weeks.



Highways Activity Log 2023 - 2024

Date Reported	Reporter (NK = Not Known)	Track No.	Fault	Location	Details	Status
11.04.2023	Dick	21663632	Potholes	Trade Street at Entry to Grooms Cottage	1 major and 2 minor potholes rapidly worsening since implementation of lay-by parking	12.04.2023: Marked for filling.
13.06.2023	Collins	Personal letter to EWPC	Potholes	Gravelly Close, North End , RG20 0BG	Ongoing lack of road maintenance by BDBC despite apparent adoption over 10 years ago.	Referred to Cllr Falconer (BDBC) for investigation/action.
20.07.2023	Dick	21683510	Overgrown hedgerow	Link lane at North end of Broadlayings triangle	Excessive roadside overgrowth progressively obliterating lane passage	24.07.2023: HCC inspection has shown that the issue does not require action at this time.
25.07.2023	Dick	21684159 (See also 104554122)	Degraded and sunken manhole cover	Abbey Wells Road	Cover surround severely eroded with deep degradation to road surface. Possibly resulting from excessive water flow down roadside verge and then into manhole surrounds	12.09.2023: Sunken manhole covers reset and correctly mounted, though water still flowing down road from Malverleys. Closed
26.11.2023	Dick	21702963	Multiple potholes	Hollington Lane (East End to Brick Kiln Farm)	Multiple potholes and eroded carriageway shoulder of danger to cyclists and smaller vehicles	01.12.2023: HCC: <i>We have completed any necessary actions relating to the initial enquiry or reported problem and the enquiry has now been closed.</i>
08.12.2023	Dick	SSE: # 231208-000651	Uncleared work materials and debris	Woolton Hill Surgery	Safety barriers and excavation debris left blocking car park spaces in Doctors' surgery car park following cable supply repairs. EWPC direct contact to SSE requesting early resolution to help maintain traffic flow on Trade Street.	15.12.2023: Work area cleared and car park returned to full capacity.
07.02.2024	Dick	21718913 & 7140412	Degradation of road shoulders	Abbey Wells Road – East End to Woolton Hill	Multiple areas at edge of road with significant drop off resulting from heavy vehicle damage. Considered to be dangerous to low clearance vehicles.	19.02.2024: HCC <i>“Our inspection has shown that the issue you have reported does not require action at this time.”</i>



Highways Activity Log 2023 - 2024

Date Reported	Reporter (NK = Not Known)	Track No.	Fault	Location	Details	Status
18.02.2024	Dick	106697184	Surface water flowing through East End	Abbey Wells Rd East End to Woolton Hill	Mail to HCC regarding blocked culverts and ditch gratings resulting on surface flow of water with entry into foul water system	18.03.2024: HCC Update requested. Further service ID: 106772925 Report also to Thames Water (Ref: 00581126) 20.03.2024: Referenced by HCC as 7140412 and closed as "defects do not meet our safety investigatory levels" .
20.02.2024	Dick	21722217	Multiple potholes	Tile Barn Row	Line of potholes along crown of road with one of considerable depth	15.03.2024: HCC: <i>Works have been undertaken to address the issue</i>
28.02.2024	Dick	21724647	School warning lights constantly flashing	Woolton Hill Road, adj recreation ground	Both amber lights flashing at all times.	29.02.2024: Mail from HCC disclaiming responsibility for "street lighting" by "developer" . Further clarifying mail to HCC. Tracker states "Enquiry closed". 04.03.2024: Tel to HCC ("May") to again point out that it is not street lighting but a School Warning Sign. Will now be referred for action.
07.03.2024 Follow-ups 25.03.2024 02.04.2024	Dick Dick	24248421 As above	Multiple redundant roadworks signs. Many signs still strewn beside road	East End / Stargrove Lane/ Chalk Pit Hill	Hazard cones, sandbags and warning signs have left at various points on the back lanes following roadworks. Advised HCC that may consider referral to B&DBC under "fly-tipping" FPN terms Pictures of remaining signs from East End to Heath End re-attached	22.03.2024: HCC <i>"Enquiry initially assessed, and now need to undertake further investigations into the problem."</i> 16.04.2024: Passed by GD to Cllr Thacker for HCC escalation. 24.04.2024 HCC: <i>" Following a review of your enquiry, all necessary actions have been undertaken."</i> GD: Checked all debris removed.



Highways Activity Log 2023 - 2024

Date Reported	Reporter (NK = Not Known)	Track No.	Fault	Location	Details	Status
25.03.2024	Dick	21731781	Pothole in patched road surface.	Abbey Wells Road, Woolton Hill, close to bus stop	Degradation occurring in already patched surface with hazard to vehicles and especially to bicycles	20.04.2024 Hole patched
18.04.2024	Dick	21737218	Highway shoulder degrading	Hatch House Lane, North End	Ditch failure and under-running of road surface => progressive collapse of highway shoulder with breadth of highway no longer accommodating wider wheel base vehicles	18.04.2024 HCC: <i>Passed to an Engineer, who will undertake an inspection of the site.</i> 29.05.2024: <i>enquiry is progressing and will be assessed by a member of the Hampshire County Council Highways team.</i>
18.04.2024	Dick	21737224	Damaged/Missing Inspection covers	North End Lane. North End	Multiple hazards of roadside drainage inspection covers broken or missing, including fully open drop into hidden culvert.	18.04.2024: HCC: Will be assessed by a member of the Hampshire County Council Highways team. 11.06.2024: The issue that you raised has been inspected and works are required. To be scheduled.
02.06.2024	Jones / Dick	21688983 / 21745153	Overgrowth of trees/bushes on blind bend with possible parking hazard opposite	Station Road, Woolton Hill	Follow-up on report 21688983. Hedgerow and trees now in full growth on blind bend causing hazardous conditions for cyclists and pedestrians. Sometimes exacerbated by cars/vans parked outside Old Station House.	21.06.2024: HCC inspection reports that the issue does not meet its risk-based safety criteria so matter closed
02.06.2024	Dick	Via Whats App to Thames Water with pics.	Recently installed Raised Sluice Valve Cover	Brownies Corner, Woolton Hill	Reported tripping over raised cover especially at dusk. Will become more dangerous when surrounding grass regrows. It is not clear how to report this hazard	04.06.2024: Tel: Thames Water who determine this a freshwater valve. Referred by email to Southern Water for attention. Ref WCS5028052 17.06.2024 Call from SW to identify nature of problem.



Highways Activity Log 2023 - 2024

Date Reported	Reporter (NK = Not Known)	Track No.	Fault	Location	Details	Status
12.06.2024	Dick	24251100	Uncut verges/road triangles	Esp. North End	Enquiry ref cutting of verges from parishioner, to whom responsibility/policy of HCC explained. HCC/C.Councillor contacted for update on current cutting programme.	Email to D. Beasant (HCC Highways); onward referred to Roads Maintenance. 17.06.2024: enquiry progressing and will be assessed by a member of the Hampshire County Council Highways team. 24.06.2024: HCC response - cutting of the 1meter swathe required for visibility purposes due this month. Scheduled cut of full width of the verges will be undertaken in the autumn, from September onwards. Further cuts may be made to maintain visibility. No increase in cut frequency, due to "current financial climate".
19.06.2024	Boast		Speeding	Ball Hill to derestriction at Furze Bush	Complaint of multiple speeding incidents + accident	Advised of Speed Indication Device (SID) rota and possible additional location exiting Ball Hill. Onward report and notification to HCC regarding possible reposition of SID.