

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✗	Gravel from path on surface	L	3 months
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	✓			
Roundabout	✓			
Spring See-Saw	✓			
2Bay Swing	✓			

**Date** 23rd May 2024 **Time Completed** 12:00am

**Weather Conditions** Dry, Overcast

**Additional Observations**

Signature CJ Ling

Name CJ Ling

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion Inc fire extinguishers	✓			
Defibrillator – solid icons displayed	✓			
Sewerage Plant (Listen and warning light)	✓			
Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓	Small tree down at South West corner	L	
Bins	✗	Black bin in car park not emptied		

**Weather Conditions**      **Dry, Overcast**

**Additional Observations**

Signature      CJ Ling      Name      CJ Ling

**Date**      **23<sup>rd</sup> May 2024**