AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General Environment	✓			
Floor surface	\checkmark			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	√			
Roundabout	✓			
Spring See-Saw	√			
2Bay Swing	✓			

Data	244 1/101/2024	Time Completed	2.00
Date	3rd May 2024	Time Completed	3:00bm

Weather Conditions Dry, Overcast

Additional Observations

Signature CJ Ling Name CJ Ling

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	√			
Pavilion Inc fire extinguishers	✓			
Defibrillator – solid icons displayed	√			
Sewerage Plant (Listen and warning light)	√			
Container	√			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓	Small tree down at South West corner	L	
Bins	√			

Weather Conditions D	ry, Overcast
----------------------	--------------

Additional Observations

Signature CJ Ling Name CJ Ling

Date 3rd May 2024