## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General Environment	<b>✓</b>			
Floor surface	<b>✓</b>			
Signs	<b>✓</b>			
Gates	<b>✓</b>			
Fences	<b>✓</b>			
Benches	<b>✓</b>			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	<b>✓</b>			
Multi Play	<b>√</b>			
Roundabout	<b>√</b>			
Spring See-Saw	<b>√</b>			
2Bay Swing	<b>√</b>			

Date	16 <sup>th</sup> October 2024	Time Completed	12:20pm

Weather Conditions Dry, Overcast

**Additional Observations** 

Signature CJ Ling Name CJ Ling

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	<b>√</b>			
Pavilion Inc fire extinguishers	<b>✓</b>			
Defibrillator – solid icons displayed	<b>√</b>			
Sewerage Plant (Listen and warning light)	<b>✓</b>			
Container	<b>✓</b>			
Outfield	<b>✓</b>			
Site Boundaries, Fences and Hedges	<b>✓</b>			
Bins	<b>✓</b>			

Weather Conditions	Dry, Overcast
Additional Observations	

Signature CJ Ling Name CJ Ling

Date 16<sup>th</sup> October 2024