AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General Environment	✓			
Floor surface	×	Gravel from path on surface	L	3 months
Signs	√			
Gates	√			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	√			
Roundabout	√			
Spring See-Saw	√			
2Bay Swing	√			

Date	6 th August 2024	Time Completed	12:10pm

Weather Conditions Dry, Overcast

Additional Observations

Signature CJ Ling Name CJ Ling

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	√			
Pavilion Inc fire extinguishers	✓			
Defibrillator – solid icons displayed	√			
Sewerage Plant (Listen and warning light)	✓			
Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓			

Weather Conditi	ions	Dry, Overcas	it		
Additional Obse	rvations				
Signature	Clling	Nan	ne	Clling	

Date 6th August 2024