

West Moors Memorial Hall & Social Club
 Station Road
 West Moors
 Ferndown
 Dorset
 BH22 0HZ

t: +44 (0)1202 84 96 95
 e: safe@thefirepoint.co.uk
 w: thefirepoint.co.uk
 m: Unit 3 Old Manor Farm Buildings
 187 Leigh Road
 Wimborne
 Dorset
 BH21 2BT



Trusted Fire Safety
 Services | Supplies | Support

Inspection Date: 01/05/2024

Duration Test:

Emergency Lighting Inspection Report

Area	Device type	Function	Status	Comments
Hall Entrance (external)	Bulkhead	180	Passed	
Hall Entrance (external)	Bulkhead	180	Passed	
Hall Entrance	Bulkhead	180	Replaced	Battery circuit failure
Ladies W/C	Bulkhead	180	Passed	
Gents W/C	Bulkhead	180	Passed	
Hall	Suspended Strip	180	Passed	
Hall	Suspended Strip	180	Passed	
Hall	Suspended Strip	180	Passed	
Hall	Suspended Strip	180	Passed	
Hall	Bulkhead	180	Passed	
Hall	Twinspot	180	Passed	
Hall	Bulkhead	180	Passed	
Hall	Twinspot	180	Passed	Battery replaced
Hall	Bulkhead	180	Passed	
Hall	Twinspot	180	Passed	Battery replaced
Stage	Bulkhead	180	Passed	
Small Meeting Room	Bulkhead	180	Passed	Battery replaced
Stage Circulation Space	Ceiling Mount	180	Passed	
W/C Circulation Space	Ceiling Mount	180	Passed	
W/C Circulation Space	Ceiling Mount	180	Passed	
W/C Circulation Space	Ceiling Mount	180	Passed	
W/C Circulation Space	Ceiling Mount	180	Passed	
W/C Circulation Space	Ceiling Mount	180	Passed	
Side Fire Exit	Bulkhead	180	Passed	
Kitchen	Bulkhead	180	Passed	
Social Club Fire Exit 1	Signbox	180	Passed	Observed dim
Social Club Fire Exit 2	Signbox	180	Passed	Observed dim
Social Club Pool Table	Bulkhead	180	Passed	
Social Club Office	Bulkhead	180	Passed	
Social Club Bar	Bulkhead	180	Passed	
Social Club Bar	Bulkhead	180	Passed	
Social Club Gents	Bulkhead	180	Passed	
Social Club Ladies	Bulkhead	180	Passed	



Quality Assured Fire Protection.